ALARM THERMOMETER / HYGROMETER 800039

Remote Digital Thermometer and Relative Humidity (RH) Sensor

The remote ambient temperature / relative humidity sensor is mounted on a cord over 7' long. Place the highly accurate sensor inside a desiccator, refrigerator, drying or other environmental chamber and view displays of temperature or RH together with their min / max readings on the monitor outside. Select C or F and min/max temp. and %RH alarms. When these parameters are exceeded an audible alarm sounds. Stands or wall mounts. Takes 1 AAA Battery. N.I.S.T. traceable certificate of compliance available.

Dimensions: 105 x 70 x 20 mm
Weight: 3 oz (85 g)

	Range	Resolution	Accuracy
Temperature	-50~70°C & -58~158°F	0.1°C&F	±1°C, 2°F between -20~50°C, -4~122°F ±1.5°C, 3°F above 50°C, 122°F
Humidity	20~99%	1%	±4% f.s

www.eastern-energy.net

email: info@ete.co.th