



Remote Relative Humidity (RH) Monitor and Digital Thermometer - 800027

The remote ambient temperature / relative humidity sensor is mounted on a cord over 7' long. Place the highly accurate sensor inside a desiccator, refrigerator, drying or other environmental chamber and view simultaneous displays of temperature and RH outside on the large LCD. Recalls min/max readings on both parameters. C and F selectable. Stands or wall mounts. N.I.S.T. traceable certificate of compliance available.

Dimensions: 4 1/4" x 3 3/4" x 7/8" (110 x 97 x 20mm).

Weight 6 oz (170 g)



Temperature	-10 ~ 50°C 23 ~ 122°F	0.1°C&F	±1°C, 2°F
Humidity	20~99%	1%	±4% f.s.



With NIST traceable certificate of calibration 800027C



www.eastern-energy.net

Email: info@ete.co.th